
Technical Audit Form 4.0 Service Provider Smart Energy Solutions





		Project Info	mation					
Auditor Juny	Swith			This information	on has been su	R INFORMATION: pplied to us by a third party.		
Project number	2308			passing over t	his information	I Austar Realty Limited are merely n as supplied to us by others. While ormation supplied by a third party, we		
Project name	SES #2308	National Warmer Kiwi Home	8	documents ar	nd therefore to	or reviewed the records or the maximum extent permitted by Austar Realty Limited or any of its		
Climate zone	Climate Zor	ne 1		salespersons of t	or employees o	accept any responsibility for the ntending purchasers are advised to		
Audit number	2423613			conduct men	own investiga			
		Occup	ant					
Name		XXXXXX						
Contact name phor	ne numbers	KKKOSKKKKKKKKKK	XXX					
Address		29 GLENDALE ROAD, GLE	NEDEN, WAI	TAKERE 0	602			
		Detai	s					
Date reported to EECA			STATE OF THE PARTY	21/09/2020				
Appointment time				9:00 AM				
Is this a special audit?				Yes□	No			
Is this a re audit?				Yes□	NoM			
Is the Service Provider representative present?				Yes	NoD			
Name of Service Provider representative present?				& Art	hur	Cherington		
Date of audit				14-11				
Date of installation				7/09/2020				
Claim exception re-	ason:							
Service Provider Assessment documents reviewed?				Yes□	No	NAD		
Service Provider health and safety information reviewed?				Yes□	Note	NACI		
Post-installation audit document reviewed?				Yes□	NOE	N/ACJ		
10人员的共和国		Serious Installa	tion Matters					
Serious installation	matters wer	e (select only one of the follo	wing):	A Modern State of the State	milità il espirenti			
in the property of the factor	and made sa		A-0	and made g	ood			
El Found, but not made safe or good			(SY Not found					
Li i odila,	Dut <u>not</u> maat	, calle of good	The state of					
) 4								
Signed:			Name:			.10		
Met	•			2	in Su			
W		(auditor)		0		(auditor)		
		ave they been shown through				ser No□		
		n this form as the outcome o			0	er Cherrington		
Signed: & AP. Channing.			Name:	×	Hythi	er Cherrington		
(installer representative)					er mark and a .	r representative)		

Product reported to EECA: None If not reported, does existing insulation meet the programme requirements? Ceiling comments	Yes ⊻	/ No 🗆	N/A 🗫
	Level 2	Critical Conditional	Fixed on Site N/A
Underfloor			
Product reported to EECA: Mammoth Underfloor Blanket R1.5 (120.00 m2)			
Does installed product match reported product?	Yes 🗹	No 🗆	
If No, enter product name and R-value			
And is product installed correct for use as per EECA specifications?	Yeslid	No□	
Manufacturer's label present and permanently fixed on site where it can be easily found?	Ø		
All accessible areas done?	Z O		
Product installed to bottom plate of exterior walls?			
Good friction fits?	2		
Any significant gaps?	a o		
Are clearances of approximately 100mm maintained around plumbing pipe work and fittings?		GZ/	IZY
Any sagging?	10		
Any folds too big with insulation hanging below floor joist level?	回口		
Has strapping been installed correctly - if required?			図口
Has stapling been installed correctly - if required?	Ø		
Required clearance from all outer edges of surface mounted lights?			0
Does underfloor installation meet the intent of NZS4246?	Yes	No□	
Installation debris removed?	Yes	No□	
m² reported			120
m² audited match?	Yestal	No[]	
If No, enter m² determined by Auditors			

Unable to be audited One pipe clearance too small []
Underfloor comments Clearance Mede Grand (Fixed a Ste)

Ticky with This shows inhadur (ixing a remainder on Ground Vapour Barrier) Underfloor Vapour Barrier

On Ground Vapour Barrier / Underfloor Vapour Barrier reported to EECA: None

Draught Proofing Doors

Draught proofing reported to EECA: None

Not installed

Pipe Lagging reported to EECA None
Hot Water Cylinder Wrap Cylinder wrap reported to EECA:(None)
Product reported to EECA: None
Overall comments
Additional Corrective Actions Required
no exper parier as unterfloor

