

11/06/2018

JAEK PROPERTIES LIMITED
 635A Huia Road
 Parau
 AUCKLAND 0604

REPORT BACK OF SEPTIC TANK PUMP OUT AND VISUAL INSPECTION SERVICE

PROPERTY ADDRESS: 71 CORNWALLIS RD, CORNWALLIS
SYSTEM TYPE: Standard

Dear Sir/Madam

As you will be aware, an Auckland Council Contractor has recently carried out a pump-out of your septic tank. During your pump-out, a visual inspection of your tank and drainage field was undertaken and this is the report of that inspection.

Date of Pump-out 07/05/2018 Work Order 412895 Tank ID 19990841

PUMP OUT INFORMATION

Information	Routine	
Rescheduled required		Schedule Details
Comments		

ASSET DATA

Type	Standard	Other (Specify):	
Size (litres)	4050 litres	Other (Specify):	
Material	Concrete		
Lid Depth	Ground level	Below Ground (Specify Depth):	
Risers Required	No	Details:	
Effluent Filter	No	Baffles	No
Sludge/Scum Depth		Measured with Sludgeometer	No
Scum Depth (mm)	700	Sludge Depth (mm)	250
Hose Length	<=50 metres		

TANK CONDITION AND DEFECTS

Condition Good	Yes	Details:
Defects Identified	None	Details:

COMPLETION

Lid Sealed	Yes	Comments:
Cleanup Completed	Yes	

septic.tank@aucklandcouncil.govt.nz

(09) 3010101

Infrastructure and Environmental Services

Healthy Waters Operations West

Yours sincerely

Comments

GENERAL INSPECTION COMMENTS

Defects Identified Details:

DRAINAGE FIELD DEFECTS

Drainage Field Suitable
All Components Accessible For Maintenance
(incl. risers, monitoring ports, distribution box)
All Components in Good Condition
Distribution Box
Details if Box Leaks

DRAINAGE FIELD CONDITION

Field Found	No	Comments:
Drainage Field Type	Unknown	Other (Specify):
Separate Grey Water System	Unknown	
All Pipes Into Gully Traps	Yes	

DRAINAGE FIELD DATA

Comments:

GENERAL PUMPOUT COMMENTS

(Notes on any other related issues).