STATEMENT OF PASSING OVER INFORMATION:
This information has been supplied to us by a third party.
Accordingly the Vendor and Austar Realty Limited are merely
passing over this information as supplied to us by others. While
we have passed on this information supplied by a third party, we
have not checked, audited, or reviewed the records or
documents and therefore to the maximum extent permitted by
law neither the Vendor nor Austar Realty Limited or any of its
salespersons or employees accept any responsibility for the
accuracy of the materials, intending purchasers are advised to
conduct their own investigation.



Ph: 0800 766 463 info@buildinginspect.co.nz www.buildinginspect.co.nz Licensed Building Practitioner BP111069

## SAFE AND SANITARY REPORT

DATE: **23/10/2025**CLIENT NAME: **Lance Tarrant** 

\_\_\_\_\_

ADDRESS: 30 Tane Road Laingholm



**OBJECTIVE**: Building structures and alterations in New Zealand having been done before the new building Code of Compliance regulations came into force in 1992. Ensure the structure is safe and sanitary. Safe and sanitary report is not a letter of acceptance. A safe and sanitary report is a report provided by an independent inspector stating if a building is safe and sanitary.

## **DESCRIPTION:**

To carry out a Safe and Sanitary inspection of the bathroom on south-west corner of the above address.

GENERAL CONDITION OF BATHROOM AREA			Yes	
	Yes No			
Building is tructurally sound	✓	Has adequate room division	✓	
Is clean, sanitary, well maintained	✓	Has adequate water supply	✓	
Has adequate walls, floors, ceilings	✓	Has adequate water system	✓	
Has proper ceiling heights	✓	Waste & storm water discharge correctly	✓	
BATHROOM FEATURES				
	Yes N	No	Yes	
	1 1	•		

	162	INO		res
Has separate bathroom area	✓		Has proven ventilation to outside	✓
All fixtures in good working order	✓		Tub/shower has hot/cold water	✓
All fixtures connected to sewer	✓		Lavatory flushes correctly	✓
Provides privacy to user	✓			
Has proper lighting	✓			

## **BATHROOM PASSES INSPECTION**

I have inspected the bathroom at the address above. Based on the criteria the bathroom appears to conform to the standards for safe and sanitary housing. The sole purpose of the inspection is to determine if the bathroom is safe and sanitary.

Date of Inspection: 23/10/2025 Inspector: Damon Schubert

Bryan Schubert Company Director

B.S. Seletato



No

No